

Office Memo

TO: File

FROM: Gary F. Kulibert

SUBJECT: Lehrer's Landfill Site

DATE: September 7, 1976

8-24-76

At the time of the inspection it appeared that the landfill site was being operated in conformance with the Codes. The abandonment of adjacent site areas appeared to be acceptable. Erosion did not appear to be a serious problem at this time.

  
\_\_\_\_\_  
Gary F. Kulibert

GFK:jh

*In. Buchanan Outagamie Co.  
L.F.*

OFFICE MEMO

September 7, 1976

SUBJECT: Leher Landfill - Kaukauna, Wisconsin → *FILE Solid waste*  
FROM: Terrence L. Gardon

On August 31, 1976, I inspected the Leher landfill located in Kaukauna, Wisconsin at approximately 6:30 a.m. At that time all refuse from the previous day was adequately covered. One load of refuse had been deposited in the fill area already that morning. A compactor tractor was working in the fill at the time.

*Terrence L. Gardon*  
Terrence L. Gardon  
Natural Resource Technician

TLG:sh

01031

EVALUATION	YES		NO		YES		NO		YES		NO		YES		NO		YES		NO		YES		NO	
	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO
1. Acceptable Sign Posted?	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>	
2. Adequate Screening Present?	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>	
3. Acceptable Gate Present?	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>	
4. Attendant In Accordance?	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>	
5. Insects & Rodents Controlled?	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>	
6. Windblown Material Controlled?	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>	
7. Active Area Confined?	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>	
8. All-Weather Roads Provided?	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>	
9. C & C Appear Adequate?	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>	
10. Surface Water Diverted?	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>	
11. Leachate Absent Or Controlled?	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>	
12. Unauthorized Wastes Absent?	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>	
13. Open Burning In Accordance?	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>	
14. Adequate Firebreaks Present?	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>	
15. Date & Time Of Inspection	9-3-76 11:15 AM		10-8-76 11:00		11-8-76 10:00		12-3-76 11:30 AM		1-3-77 10:00		2-20-77 4:15 PM		6-2-77											

COMMENTS: Leachate streams present 9-3-76

12-16-76 Post covering, site did not look good. Could not see gate  
 3-15-77 Much surface water in creek  
 6-2-77 Removal of surface water in creek

00837



TN Buchanan  
Lehrer

OFFICE MEMO

September 2, 1976

FROM: Gary F. Kulibert  
SUBJECT: Lehrer's Landfill

I have reviewed the Soil Testing Service of Wisconsin report on the proposed Lehrer landfill site located in Kaukauna, Wisconsin. Based on my review it appears that the site does have potential for development as a landfill site. There is adequate clays overbed rock which would eliminate any potential contamination of ground water in this area. However, while investigating a recent complaint I feel the plans have failed to indicate a unique situation on the north end of the landfill site. This is especially true considering that the topography does not extend in that direction. Recently we inspected a complaint and found leachates seeping from the side of a hill approximately 250 feet north of the present active area. Conductivity reading was taken which indicated better than 200 <sup>µ</sup>MHOS. In talking to residents in the area apparently ~~an~~ <sup>the</sup> old ravine had been filled with refuse and then covered. These leachate seeps began after Mr. Lehrer began excavating and disposing in ~~this~~ <sup>the</sup> present area. I feel this problem must be addressed both in the hydrogeologic study as well as the re-engineering.

Besides the above-mentioned problem I do not foresee where the site, if properly operated, will contribute significantly to any environmental degradation.

  
Gary F. Kulibert

GFK:sh

01030